

R291 F132-143

Lot 2		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$271.50
Blk Bounded by 27th, 28th, U, & V Streets					
TYPE BUILDINGS					
PERMIT NO.	LOCATION				
G-9141	2710 - U Street				A-2 (19)
DATE	PURPOSE				
11-12-70	Construct 16-unit apartment house				
ZONE	OWNER				
	E.K. Purdy, 1060 Sandbar Circle, Carm.				
R-4	ARCHT				
	M.R. List, Sacto.				
	CONTR				
	Owner		Same		
VAL. \$145,000.	STORIES	ROOMS	APTS.	SIZE	
	2		16	13,175-sq.ft.	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
		V-No hour	H-1	483-7521	
FORM	11/23/70	<i>[Signature]</i>			
JOIST					
FRAME	1-14-71	<i>[Signature]</i>			
SHEET					
ROCK	1-22-71	<i>[Signature]</i>			
FINAL	2-25-71	<i>[Signature]</i>			

[Signature]
 cert. call sent

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<i>1-18-70</i>
11-18-70	<i>OK slab</i>
12-24-70	<i>P.T. Roof nail - Short on nails - Barbits</i>
12-30-70	<i>OK roof nail</i>
1-14-71	<i>Span not ready - OK to install</i>
1-15-71	<i>Span frame - Not ready</i>
1-18-71	<i>Span frame backing lining missing - called time wrong</i>
	<p data-bbox="266 855 394 912">COMPLETE AND OK</p> <p data-bbox="1158 886 1294 912">INSPECTOR</p>