

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA	FINAL INSPECTIONS	
		79 Glenville Circle				1		
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE
Lot 1045 Glenbrook #10								
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	
GEN. CONTR. Besco			Same				383-9315	
ELEC. CONTR.								
PLBG. CONTR.								
MECH. CONTR.								
ARCH. ENGR.								
OWNER Mattbrook, Inc.			2777-Alvarado St. San Leandro					
CONST. LOAN LENDER								
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOMS	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE
			1	5	456-garage	1,383 sq. ft.		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED

NATURE OF WORK:- Const. dwlg. & att. garage Plan 100

PERMIT NO. S.P. G-2318	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 252	FRAME NO:- 562	TO
ISSUANCE DATE 1/9/69	INSPECTION RECORD	REEL NO. 229	FRAME NO:- 60	TO 70
VALUATION \$ 13,900.00	JOB FILE	REEL NO.	FRAME NO:-	TO
R.U.F. FEE \$				
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$ 49.00	REMARKS AND/OR VARIANCES			
\$	DWELLING			
\$				
TOTAL FEES \$	Dwelling			

2507F280 - final

