

RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY | DATE |
|---------|------------------------------|-------------------------|---|---------------------------------|------------------------------------|---|--|
| 1-22-75 | Elect. \$300 | C-484 \$10. | New Service Dwlg | Mr Myers | All Electric 2316 Thelma Avenue | <i>EP 3900</i> <i>Syllian</i> | 3-5-75 |
| 3/30/79 | E. \$ 50.00 | G-2686 \$ 7.50 H2418 | Repair meter service to Dwlg Bldg. | Thomas Elliott 3001 P St. | Owner Same 95816 | Charles | 5-15-79 E |
| 4/3/79 | B.M.P.E. \$ 200.00 | G-2776 \$ 20.00 | 01. Replace Marlite in shower, board up window. 2. Wire rear bldg to code(or Terminate) 3. Bring wiring in attic to be within 6' of crawl space & to code. 4. Cover bedroom panel&G2686 5. Install fan. 6. Water heater checked & corrected if necessary-Dwlg | Thomas. F. Elliott 3001 P St | Owner Same 95816 | Petralli Petralli Charles Petralli | 5-16-79 B 5-15-79 E 5-18-79 P 5-16-79 M |

MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|------------|---------------------|------------|---------------------|------------|---------------------|
| C-484 | R404F040 | | | | |
| C-484 | R403F006 final | | | | |
| G-2686 | R564F338 | | | | |
| G-2776 | | | | | |
| G2686 | R572F477 final | | | | |
| G2776 | R572F477 final | | | | |

