

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-25570.</i>	LOCATION <i>1130 - 2nd street</i>
DATE <i>11-2-49.</i>	PURPOSE <i>Repairs to bldg.</i>
ZONE	OWNER <i>Dr. Oliver</i>
	ARCH'T.
	CONTR. <i>D. Tatta.</i>

VAL. <i>\$ 300</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
12/13/49	Final Insp. C. E. Buckner
	COMPLETE AND O. K. INSPECTOR