

B123 7221-228

Lt. 163

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$52.00

Greenhaven #70 Unit #1 **TYPE BUILDINGS**

PERMIT NO. E-4158		LOCATION S19 - Parklin Avenue		A-3	
DATE Jun 12-63		PURPOSE Const. dwelling & attached garage			
ZONE R-1		OWNER Lee Basford		6321-Eichler Way	
		ARCH'T Owner		Same	
		CONTR Owner		421-1209	
VAL. \$14,100.		STORIES 1	ROOMS 6	APTS. 525-gar.	SIZE 1,461 sq.ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	<i>6-18-63</i>	<i>Basford</i>			
JOIST	<i>6-24-63</i>	<i>Basford</i>			
FRAME	<i>7-11-63</i>	<i>Basford</i>			
SHEET ROCK	<i>7-22-63</i>	<i>Basford</i>			
FINAL	<i>8-22-63</i>	<i>J. Basford</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
6-14-63	PT. on steel for Parlor & fireplace. Birds
7-9-63	PT. Poor workmanship. Hall "out of plumb". Birds
7-10-63	PT. Ceiling joint in living room over fireplace. Hammer
8-21-63	PT. Gut roof. Callaway
COMPLETE AND OK	INSPECTOR