


*K 251 F 90-93*

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$32.00

TYPE BUILDINGS

Double Fee

PERMIT NO. <b>G-2131</b>	LOCATION <b>1326 - Silica Avenue A-6 (55.02)</b>				
DATE <b>Dec-9-68</b>	PURPOSE <b>Install flooring on mezzanine in warehouse</b>				
ZONE	OWNER <b>Wm. Belcher Same /building.</b>				
	ARCH'T <b>Leo Mc Glade Sacto.</b>				
	CONT'R <b>Aldonco Const. Co. 2701 - Cottage Way</b>				
VAL. <b>\$3,000.</b>	STORIES	ROOMS	APTS.	Suite 12 SIZE	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) F-2 483-3491	
FORM					
JOIST	<i>12-17-68</i>	<i>Stamens (initials)</i>			
FRAME					
SHEET HOOK					
FINAL	<i>1-30-69</i>	<i>E. Paise</i>			<i>JWT</i>



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-16-68	A Grouts not checked & OK.
	2x12 not bolted to beam. Simmons
12-24-68	No fixit Simmons
1-15-69	A not ready Larson
	<div style="display: flex; justify-content: space-between;"> <span>COMPLETE AND OK</span> <span>INSPECTOR</span> </div>

