

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-20003</i> DATE <i>4-21-50.</i> ZONE	LOCATION <i>3517 Santa Cruz Way</i>
	PURPOSE <i>Addn to garage</i>
	OWNER <i>E. Lawrence</i>
	ARCH'T,
	CONTR, <i>Owner</i>

VAL. <i>\$ 250</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK-REMARKS
5/6/50	Forms insp. <i>M.A. Shumway</i>
9-27-50	Frame (truss ratters) need stiffening & vents are apt in <i>M.A. Shumway</i>
10-6-50	Frame <i>M.A. Shumway</i>
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>