

B148 7311

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$5.00

**TYPE BUILDINGS**

PERMIT NO. E-7746		LOCATION 2801 - San Luis Ct. A-2			
DATE Jul 6-64		PURPOSE Repair termite damage to dwlg.			
ZONE R-1		OWNER John Matsumoto Same			
		ARCH'T GA 1-4960			
		CONT'R Midstate Termite Control 7350-Garden			
VAL. \$200.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	8-4-64	<i>Hammond</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
7-14-64	PT. NO permit Card on Job - no plans - Hammer
COMPLETE AND OK	INSPECTOR