

R-53

Lot 115 BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD F115-119

Riverside Estates#2 TYPE BUILDINGS \$41.00

| | |
|----------------------|---|
| PERMIT NO. D-1266 | LOCATION 920- Roeder Way |
| DATE Mar. 12, 59 | PURPOSE Const dwelling & att. garage |
| ZONE R-1 | OWNER R. S. Taylor |
| | ARCH'T |
| | CONT'R Owner GL 5-9285 |

| | | | | |
|----------------|--------------|------------|-------|-------------------------------|
| VAL. \$14,100. | STORIES 1 | ROOMS 6 | APTS. | 500 Gar. SIZE 1424 Sq. ft. |
|----------------|--------------|------------|-------|-------------------------------|

| INSP. | DATE | INSPECTOR |
|-------|-----------|---------------------|
| FORM | 3 MAR 59 | <i>R. S. Taylor</i> |
| JOIST | 23 MAR 59 | <i>R. S. Taylor</i> |
| FRAME | 16 Apr 59 | <i>R. S. Taylor</i> |
| LATH | 22 Apr 59 | <i>R. S. Taylor</i> |
| FINAL | | |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|------|------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |
| | INSPECTOR |