

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 3963</i>	LOCATION <i>906 - Robertson Way</i>			
DATE <i>7/12/40</i>	PURPOSE <i>New build & gar</i>			
ZONE <i>—</i>	OWNER <i>Louis J. Bennett</i>			
	ARCH'T.			
	CONT'R. <i>Owner</i>			
VAL <i>4x10</i> ✓	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

.DATE.	CONDITION OF WORK-REMARKS
7/16-40	1 st Amp Forms of Poles
8/7/40	2 nd N.S.P. Frame in place ^{OK} R.W. Campbell
8/14/40	3 rd N.S.P. INT & EXT LATH ^{OK} R.W. Campbell
10/23/40	4 th N.S.P. DOLG & GARAGE Completed ^{OK}
	R.W. Campbell
10/23/40	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. Allice W. Campbell INSPECTOR </div>