

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-17945</i>	LOCATION <i>6118-2nd Ave</i>
DATE <i>1/24/44</i>	PURPOSE <i>Garage attached to house remodel</i>
ZONE	OWNER <i>Paul C. Hollenbeck</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>16000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
12/7/42	2 ND WSP. Found 4 copper wire attached to ground. 3000. A.W. Campbell
	3 RD WSP. Short circuit in the line.
2/12/45	4 TH WSP. Alterations & Repairs Completed OK A.W. Campbell
	/
2/2/45	COMPLETE AND O. K. <i>Alden W Campbell</i> INSPECTOR