

5408 Bradford Drive
RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
10-18-74	Bldg. Elect. \$5,000	B-8140 \$46.	Fire Damage Repair Dwelling	D.P. Turpen	Owner	B. Biolo	3-1-76
			<i>(See D-2793 & B-9346 per Vachy)</i>				<i>all photos cancelled as per zim/boone</i>
11-26-74	M.E. \$400.	B-9346 \$10	Install dural furnace Dwelling	D. P. Turpen	DeV Parnell Htg & A/C	Sullivan	4-27-76
		<i>G0109</i>			2425 Q St., R. L.	Vachy	6-28-76
4-22-76	BMPE \$500.	D-2793 \$10.	Repair Fire Damage Dwelling	Bill Meeker	Owner	Sullivan	8/27/76 E
		<i>G 6194</i>		4740 71st St.		Biolo	8/22/76 B
						Vachy	12-16-76 P.M.
12-13-76	E \$100.00	D-9760 \$20.00	Install elec stove dwelling	William C. Meeker	Owner	Sullivan	1-25-77 E
		G-7817		4740 71st St.			

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
B-8140	R 397 F 359	D-9760	R466 F040		
B-9346	R 400 F 399	D-9760	R540 F402		
D-2793	R-442-F085				
J-2793	R 540 F403				
B-9346	R 540 F403				
B-8140	R 540 F403				