

R-136 F 593-597

East 65.79 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$37.00

of Lot 138

Land Park Tr. #2

TYPE BUILDINGS

|            |          |                                   |                 |               |                             |
|------------|----------|-----------------------------------|-----------------|---------------|-----------------------------|
| PERMIT NO. |          |                                   |                 |               |                             |
| E-6174     | LOCATION | 1064 - Teneighth Way              |                 | A-2           |                             |
| DATE       | PURPOSE  | Const. dwelling & attached garage |                 |               |                             |
| Feb. 7-64  | OWNER    | Ralph Francis 1232 - 43rd Street  |                 |               |                             |
| ZONE       | ARCH'T   |                                   |                 |               |                             |
| R-1        | CONTR    | Owner                             |                 | Same          |                             |
| VAL.       | \$9,300. | STORIES                           | ROOMS           | APTS.         | 360-gar. SIZE<br>990 sq.ft. |
|            |          | 1                                 | 4               |               |                             |
| INSP.      | DATE     | BLDG. TYPE                        | OCCUPANCY GROUP | PHONE (O) (C) |                             |
| FORM       | 2-18-64  | Barbato                           |                 |               |                             |
| JOIST      | 3-11-64  | Pills                             |                 |               |                             |
| FRAME      | 4-17-64  | Quint                             |                 |               |                             |
| SHEET ROCK | 4-23-64  | Quint                             |                 |               |                             |
| FINAL      | 7-8-64   | R. J. [Signature]                 |                 |               |                             |

| DATE               | SPECIAL CONDITIONS OF WORK — REMARKS                        |
|--------------------|---|
| 3-2-64             | Plumbing not in double<br>ends of floor joist <i>Rising</i> |
| 4-16-64            | P.T. not ready. <i>P.T. East</i>                            |
| 6/30/64            | P.T. no pitched vent <i>County</i>                          |
|                    |   |
|                    |   |
|                    |   |
|                    |   |
|                    |   |
|                    |   |
|                    |   |
| COMPLETE<br>AND OK | INSPECTOR   |