

**RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA**

PROPERTY PARCEL NO.		JOB ADDRESS				INSPECTION AREA	FINAL INSPECTIONS		
		3733 Belden St.				6			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	
Block 19 Del Paso Hgts. Lot 21									
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	BUILDING BY	DATE
GEN. CONTR. Owner								<i>Count</i>	<i>9-19-72</i>
ELEC. CONTR.								ELECTRICAL BY	DATE
PLBG. CONTR.								PLUMBING BY	DATE
MECH. CONTR.								MECHANICAL BY	DATE
ARCH. ENGR.									
OWNER Empire Homes			5343 Rimwood Dr.					CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
						1,142			
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	CENSUS TRCT. NO.	EXISTING BLDG'S SAME LOT	HOW USED

NATURE OF WORK:- Const. dwelling & garage MP 1142

PERMIT NO. S.P. H-6197		MICROFILM RECORD			
ISSUED BY					
ISSUANCE DATE	4-6-72	PLANS AND APPLICATION	REEL NO. 385	FRAME NO. 534	TO
VALUATION	\$ 17,600.00	INSPECTION RECORD	REEL NO. 47337	FRAME NO. 538	TO 60000
R.D.F. FEE	\$	JOB FILE	REEL NO.	FRAME NO.	TO
S.M.I. FEE	\$				
PLAN CK. FEE	\$				
SEWER INCL. FEE	\$				
PERMIT FEE	\$ 72.00	REMARKS AND/OR VARIANCES			
	\$	Dwelling			
	\$				
TOTAL FEES	\$				

