

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD  
TYPE BUILDINGS


PERMIT NO.  
80 26  
DATE  
5/14/31  
ZONE  
2<sup>nd</sup> Am.

LOCATION  
152 MK 33  
500 Palm Dr  
PURPOSE  
Residence garage  
OWNER  
M. Lund  
ARCHT  
CONT-R

PHONES

VAL. 5000 - | STORIES 1 | ROOMS 6 | APTS. 1 | SIZE 37x44-22

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
5/14/31	1 <sup>ST</sup> /NSP. Basement Forms. Garage to line up with side of house - In "Reverse" frontage as no lots are located between this lot and lot of rear of same M.W. Campbell
5/15/31	1 <sup>ST</sup> /NSP. EXT. WALL FORMS O.K. M.W. Campbell
5/19/31	2 <sup>ND</sup> Int Jamb Framing OK R.H. Reuter
5/23/31	3 " Int Text Lath OK R.H. Reuter
	<div style="display: flex; justify-content: space-between; align-items: center;"> <div data-bbox="332 882 507 936">COMPLETE AND O.K.</div> <div data-bbox="557 663 1179 955" style="text-align: center;">  </div> <div data-bbox="1229 908 1414 936">INSPECTOR</div> </div>