

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-1474</i>	LOCATION <i>541 - Pala Way</i>
DATE <i>9/12/38</i>	PURPOSE <i>General repairs add Rm attic.</i>
ZONE	OWNER <i>Geo. Almqvist</i>
	ARCH'T.
	CONTR. <i>J. Paul Howell</i>

VAL <i>7500</i>	STORIES	ROOMS	APTS.	SIZE
-----------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS
	<p data-bbox="315 932 467 977">COMPLETE AND O. K.</p> <p data-bbox="1273 949 1433 972">INSPECTOR</p>