

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|------------------------------|--|------------------|-------|------|
| PERMIT NO. <i>B-10582</i> | LOCATION <i>3239 - Riverside Blvd</i> | | | |
| DATE <i>8/6/42</i> | PURPOSE <i>Refrigerator dwlg.</i> | | | |
| ZONE | OWNER <i>Charles E. Coft</i> | | | |
| | ARCH'T. <i>Fred B. Curtis</i> | | | |
| | CONT'R, <i>Fred B. Curtis</i> | | | |
| VAL. <i>307.00</i> | STORIES | ROOMS | APTS. | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | | |
| VENT SHAFTS | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | | |
| LATH | | GAS VENTS | | |
| FIRE ESCAPES | | CHIMNEYS | | |
| STAND PIPES | | SKYLIGHTS | | |

| DATE | CONDITION OF WORK-REMARKS |
|---------|---|
| 8/27/42 | Re-shingling of Dreg with Cedar Shingles Completed - OK A.W. Campbell |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| 8/27/42 | COMPLETE AND O. K. Inspector A.W. Campbell |