

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-34347</i>	LOCATION <i>1300 - 30<sup>th</sup> St.</i>			
DATE <i>June 7-52</i>	PURPOSE <i>Re-roofing</i>			
ZONE <i>1</i>	OWNER <i>Shenkin, C. B. Inc.</i>			
	ARCH'T. <i>1</i>			
	CON'TR. <i>Owner</i>			
VAL. <i>500.00</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS	<i>wrecked</i>		ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="189 860 310 897"><b>COMPLETE AND O. K.</b></p> <p data-bbox="962 878 1089 899"><b>INSPECTOR</b></p>