

R179 76-21

Lot 8 12		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$99.50
Riverside Village		TYPE BUILDINGS		R179 7110 (rev. Regl. Desc.)	
PERMIT NO. F-1981	LOCATION 961 925 - Piedmont Drive			A-3	
DATE Oct 12-65	PURPOSE Const. dwlg. & det. gar. & cov. patio				
	OWNER Dr. & Mrs. H. Stathos	1071-Lake Glenn			
ZONE R-1	ARCH'T G.H. Klippel				
	CONTR B & T Const.	1071-Lake Glen Way 421-0561			
VAL \$31,200.	STORIES	ROOMS	APTS.	700-gar.	SIZE 3127.5 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	10-18-65	Callaway	10-31-65	Callaway	
JOIST	10-31-65	Callaway			
FRAME	1-14-66	Ripio			
SHEET ROCK	1-20-66	Ripio			
FINAL	7-13-66	Ripio			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
10-29-65	O/C slab Callaway
6-23-66	Pt Final - not open Grant
6-27-66	Pt Final - Shower doors not installed
	Fulley
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>