

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-3187</i>	LOCATION <i>1562. Santa Ynez</i>
DATE <i>6/1/39</i>	PURPOSE <i>New double garage</i>
ZONE <i>1</i>	OWNER <i>Thomas &amp; Marie Jurich</i>
	ARCH'T. <i>Devin</i>
	CON'T'R. <i>Devin</i>

VAL. <i>6000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area 1713<sup>00</sup> @ 35'</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
7/26/59	2 <sup>nd</sup> floor frame in place <sup>OK</sup> R W Campbell
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>