

17267 F 1-59

Ptn. of **BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$1,069.50

Parcel D, Book 9,  
Map 40 (See Legal)

**TYPE BUILDINGS**  
MASTER CARD *8233 F 201 - 201/101*

PERMIT NO. G-4447	LOCATION 6001 - Riverside Blvd. A-3 (40)
DATE Aug-20-69	PURPOSE Const. 94-unit Apartment complex & det.
ZONE R-3	OWNER Geo. Karadanis 3823-Marconi Ave/carpports
	ARCH'T Leo McGlade Sacto. (16-buildings)
	CONTR Owner Same 487-2570

VAL. \$950,000.	STORIES 2	ROOMS	APTS. 94	52,288 2nd flr. 48,131 sq.ft.
-----------------	--------------	-------	-------------	----------------------------------

INSP.	DATE	BLDG. V-No Hr. TYPE V-1 Hr.	OCCUPANCY GROUP H-1	PHONE (O) (C)
FORM		<i>V. Zubats</i>		
JOIST				
FRAME				
SHEET ROCK				
FINAL	<i>10/1-1/70</i>	<i>J. G. Gulak</i>		

*certificate sent out*

DATE	SPECIAL CONDITIONS OF WORK -- REMARKS
8-21-70	Roof Nail OK <i>Subs</i>
	COMPLETE AND OK
	INSPECTOR

*R-367 F1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*R-367 F-367-364 file*

**BLDG. #1**

<b>PERMIT NO.</b> G-4447		<b>LOCATION</b> 6001 - Riverside Blvd. A-3 (40)			
<b>DATE</b> Aug-20-69		<b>PURPOSE</b> Const. 10-unit apartment in apt. complex			
<b>ZONE</b> R-3		<b>OWNER</b>			
		<b>ARCH'T</b> (See master card for additional info.)			
		<b>CONT'R</b>			
<b>VAL.</b>		<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b> 10	5,597 2nd flz 4,379 sq. ft.
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. V No Hr.</b> <b>TYPE V 1 Hr.</b>		<b>OCCUPANCY GROUP</b> H-1	<b>PHONE (O) (C)</b> 487-2570
<b>FORM</b>	<i>10-6-69 Bartato</i>				
<b>JOIST</b>					
<b>FRAME</b>	<i>2-11-70 Bartato</i>				
<b>SHEET ROCK</b>	<i>9-12-70 Bartato</i>				
<b>FINAL</b>	<i>8-21-70 Bartato</i>				

*Evt*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
10-27-69	PT not ready <span style="float: right;">Boyle</span>
10-29-69	OK slab <span style="float: right;">Boyle</span>
1-6-70	OK permit by mail <span style="float: right;">Boyle</span>
1-24-70	OK interior cleaned mail <span style="float: right;">Boyle</span>
8-14-70	OK to install <span style="float: right;">Boyle</span>
8-15-70	PT not ready by mail <span style="float: right;">Boyle</span>
COMPLETE AND OK	INSPECTOR

R267 E1-59

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

R290 F-361-264 file

BLDG.#2

PERMIT NO. G-4447	LOCATION 6001 - Riverside Blvd. A-3 (40)
DATE Aug-20-69	PURPOSE Const. 4-unit apartment in apt. complex
ZONE R-3	OWNER ARCH'T (See master card for additional info.) CONT'R

VAL.	STORIES 2	ROOMS	APTS. 2,096 2nd flz
			4 2,096 sq. ft.

INSP.	DATE	BLDG. TYPE V No Hr. V 1 Hr.	OCCUPANCY GROUP H-1	PHONE (O) (C) 487-2570
-------	------	-----------------------------	---------------------	------------------------

FORM	10-6-69	Field
JOIST		
FRAME SHEET ROCK	2-11-70	partial - Barloto
	2-26-70	Barloto
FINAL	8/21/70	Barloto

Er

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
11-27-69	Pl slab not ready <span style="float: right;">Bills</span>
11-29-69	OK slab <span style="float: right;">Bills</span>
1-29-70	OK after inspection mail <span style="float: right;">Bills</span>
2-14-70	OK to install <span style="float: right;">Bills</span>
10-15-70	Pl not ready for final <span style="float: right;">Bills</span>
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="283 833 407 890">COMPLETE AND OK</span> <span data-bbox="1128 865 1259 890">INSPECTOR</span> </div>

R-267 F1-59

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

R290 F261-501/101

BLDG. #3

PERMIT NO. G-4447	LOCATION 6001 - Riverside Blvd. A-3 (40)
DATE Aug-20-69	PURPOSE Const. 4-unit apartment in apt. complex
ZONE R-3	OWNER
	ARCH'T (See Master card for additional info.)
	CONT'R

VAL\$	STORIES 2	ROOMS	APTS. 4	1,500 2nd flr. 1,500 sq. ft.
-------	--------------	-------	------------	---------------------------------

INSP.	DATE	BLDG. V No Hr. TYPE V 1 Hr.	OCCUPANCY GROUP H-1	PHONE (O) (C) 487-2570
-------	------	--------------------------------	------------------------	---------------------------

FORM 10-6-69 *Field*

JOIST 2-11-70 *Parlat - Barbato*

FRAME

SHEET  
ROCK 2-25-70 *Parlat*

FINAL 8/5/70 *Parlat* *Enc*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
10-27-69	Pt not ready      Seals
10-29-69	OK slab      Seals
1-29-70	OK exterior, cleaned, mil. Disturb
3-4-70	OK to insulate      Seals
6-15-70	Pt not ready for final slab
COMPLETE AND OK	INSPECTOR



*K 367 E1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*R290 East 2nd St*  
**BLDG. #4**

<b>PERMIT NO.</b> G-4447	<b>LOCATION</b> 6001 - Riverside Blvd. A-3 (40)
<b>DATE</b> 8-20-69	<b>PURPOSE</b> Const. 8-unit apartment in apt. complex
<b>ZONE</b> R-3	<b>OWNER</b>
	<b>ARCH'T</b> (See master card for additional info.)
	<b>CONT'R</b>

<b>VAL.</b>	<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b> 8	<b>4,192 2nd fl.</b> <b>4,192 sq. ft.</b>
-------------	---------------------	--------------	-------------------	--

<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b> V No Hr. V 1 Hr.	<b>OCCUPANCY GROUP</b> H-1	<b>PHONE (O) (C)</b> 487-2570
--------------	-------------	---------------------------------------	----------------------------	----------------------------------

<b>FORM</b>	<i>10-3-69 (file)</i>			
<b>JOIST</b>				
<b>FRAME</b>	<i>2-10-70</i>	<i>Barbato</i>		
<b>SHEET ROCK</b>	<i>2-15-70</i>	<i>Barbato</i>		
<b>FINAL</b>	<i>8/21/70</i>	<i>Barbato</i>		

*Enc*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
10-27-69	Pt not ready <span style="float: right;">Rich</span>
11-3-69	Pt not ready <span style="float: right;">Rich</span>
11-3-69	Pt not ready <span style="float: right;">Rich</span>
1-6-70	pk circuit, heavy mil <span style="float: right;">Rich</span>
1-29-70	pk circuit, plywood wall <span style="float: right;">Rich</span>
2-4-70	pk to install <span style="float: right;">Rich</span>
COMPLETE AND OK	INSPECTOR

*R-269 F-1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*R-240 F-261 241/242*

**BLDG. #5**

<b>PERMIT NO.</b> G-4447	<b>LOCATION</b> 6001 - Riverside Blvd. A-3 (40)
<b>DATE</b> Aug-20-69	<b>PURPOSE</b> Const. 6-unit apartment in apt. complex
<b>ZONE</b> R-3	<b>OWNER</b>
	<b>ARCH'T</b> (See master card for additional info.)
	<b>CONTR</b>

<b>VAL.</b>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>5,382 sq. ft.</b>
	2		6	2,556 sq. ft.
<b>INSP.</b>	<b>BLDG. TYPE</b>	<b>V No Hr.</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
		V 1 Hr.	H-1	487-2570
<b>FORM</b>	<i>10-8-69 [Signature]</i>			
<b>JOIST</b>				
<b>FRAME SHEET ROCK</b>	<i>3-20-70 [Signature] 3-24-70 [Signature]</i>			
<b>FINAL</b>	<i>8/31/70 [Signature]</i>			

*Enc*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
11-3-69	OK wall ready <span style="float: right;">next</span>
11-13-69	OK slab <span style="float: right;">Blumrose</span>
5-6-70	OK partial N.Y.R. wall rail <span style="float: right;">F. H. H.</span>
	<div style="display: flex; justify-content: space-between;"> <span>COMPLETE AND OK</span> <span>INSPECTOR</span> </div>

R-267 F1-59

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

R. 340 F. 301-204 jlt

BLDG. #6

PERMIT NO. G-4447	LOCATION 600E - Riverside Blvd. A-3 (40)
DATE Aug-20-69	PURPOSE Const. 12-unit apartment in apt. complex
ZONE R-3	OWNER
	ARCH'T (See master card for additional info.)
	CONT'R

VAL.	STORIES 2	ROOMS	APTS. 12	6,698 2nd flr. 5,588 sq. ft.
------	--------------	-------	-------------	---------------------------------

INSP.	DATE	BLDG. TYPE	V No Hr. V 1 Hr.	OCCUPANCY GROUP	PHONE (O) (C)
				H-1	487-2570

FORM 10-8-69 *Risks*

JOIST

FRAME 3-11-70 *Barbato* 3-12-70 *Barbato*

SHEET ROCK 3-18-70 *Eastman Barbato* 3-19-70 *Barbato*

FINAL 8/31/70 *Barbato* *Em*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
11-3-69	24 Ret ready	Gold
11-13-69	OK. ok	Fluorescence
1-15-70	OK. Long rail	Barbit
3-24-70	OK. partial pressure, etc.	Barbit
4-7-70	OK. OK	Ink
	COMPLETE AND OK	INSPECTOR

R-367 F1-59

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

R 290 F361 2001 JPL

BLDG. #7

PERMIT NO. <b>G-4447</b>	LOCATION <b>6001 - Riverside Blvd. A-3 (40)</b>				
DATE <b>Aug-20-69</b>	PURPOSE <b>Const. 4-unit Apartment in apt. complex</b>				
ZONE <b>R-3</b>	OWNER				
	ARCH'T <b>(See master card for additional info.)</b>				
	CONTR				
VAL.	STORIES <b>2</b>	ROOMS	APTS. <b>4</b>	<b>2,268 2nd flr.</b>	
				<b>2,268 sq. ft.</b>	
INSP.	DATE	BLDG. TYPE	V No Hr. <b>V 1 Hr.</b>	OCCUPANCY GROUP	PHONE (O) (C) <b>H-1 487-2570</b>
FORM	<b>10-8-69</b>	<b>Barbato</b>			
JOIST					
FRAME	<b>3-9-70</b>	<b>Barbato</b>			
SHEET ROCK	<b>3-12-70</b>	<b>Barbato</b>			
FINAL	<b>8/11/70</b>	<b>Barbato</b>			

Eva

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
11-18-69	OK slab <span style="float: right;">Risks</span>
1-15-70	OK spray mud <span style="float: right;">Bustments</span>
	COMPLETE AND OK <span style="float: right;">INSPECTOR</span>



*R-267 F1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*2570 East - 36th St*

**BLDG. #8**

<b>PERMIT NO.</b> G-4447		<b>LOCATION</b> 6001 - Riverside Blvd. A-3 (40)			
<b>DATE</b> Aug-20-69		<b>PURPOSE</b> Const. 4-unit apartment in apt. complex			
<b>ZONE</b> R-3		<b>OWNER</b>			
		<b>ARCH'T</b> (See master card for additional info.)			
		<b>CONTR</b>			
<b>VAL.</b>		<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b> 4	1,500 2nd flr. 1,500 sq. ft.
<b>INSP.</b>	<b>DATE</b>	<b>BLDG'V No Hr.</b> TYPE V 1 Hr.		<b>OCCUPANCY GROUP</b> H-1	<b>PHONE (O) (C)</b> 487-2570
<b>FORM</b>	<i>10-8-69</i>	<i>Riddle</i>			
<b>JOIST</b>					
<b>FRAME SHEET</b>	<i>3-9-70</i>	<i>Barbato</i>			
<b>ROCK</b>	<i>3-12-70</i>	<i>Barbato</i>			
<b>FINAL</b>	<i>8/21/70</i>	<i>Barbato</i>			

*Ent*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
11-18-69	AP slab <span style="float: right;">K. Cole</span>
	COMPLETE AND OK <span style="float: right;">INSPECTOR</span>

*R267 F1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS** *R290 F-601-264 Jelle*  
**BLDG. #9**

<b>PERMIT NO.</b> G-4447	<b>LOCATION</b> 600E - Riverside Blvd. A-3 (40)
<b>DATE</b> 10-20-69	<b>PURPOSE</b> Const. 8-unit Apartment in apt. complex
<b>ZONE</b> R-3	<b>OWNER</b>
	<b>ARCH'T</b> (See master card for additional info.)
	<b>CONT'R</b>

<b>VAL.</b>	<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b> 8	4,192 2nd fl <sup>2</sup> . 4,192 sq. ft.
-------------	---------------------	--------------	-------------------	--

<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b> V <b>No Hr.</b> V 1 Hr.	<b>OCCUPANCY GROUP</b> H-1	<b>PHONE (O) (C)</b> 487-2570
--------------	-------------	--	----------------------------	-------------------------------

<b>FORM</b>	<i>10-8-69 [Signature]</i>			
<b>JOIST</b>				
<b>FRAME</b>	<i>2-26-70 [Signature]</i>			
<b>SHEET ROCK</b>	<i>3-16-70 [Signature] 3-9-70 [Signature]</i>			
<b>FINAL</b>	<i>8/31/70 [Signature] Eng</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
11-13-69	Pl. slab	Hammer
1-7-70	Pl. 1" top rail	L. 1" top
2-20-70	Pl. 1" general wall rail	Pl. slab
	COMPLETE AND OK	INSPECTOR

*R-267 A1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*C-290 F-361 - 2nd flr*

**BLDG. #10**

<b>PERMIT NO.</b> G-4447		<b>LOCATION</b> (6001 - Riverside Blvd. A-3 (40))			
<b>DATE</b> Aug-20-69		<b>PURPOSE</b> Const. 4-unit apartment in apt. complex			
<b>ZONE</b> R-3		<b>OWNER</b>			
		<b>ARCH'T</b> (See master card for additional info.)			
		<b>CONT'R</b>			
<b>VAL.</b>		<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b> 4	<b>5,840 2nd flr. area</b> 5,840 sq. ft.
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. V No Hr.</b> <b>TYPE V 1 Hr.</b>		<b>OCCUPANCY GROUP</b> H-1	<b>PHONE (O) (C)</b> 487-2570
<b>FORM</b>	<i>10-15-69</i>	<i>Billie</i>			
<b>JOIST</b>					
<b>FRAME</b>	<i>4-6-70</i>	<i>Billie</i>			
<b>SHEET ROCK</b>	<i>4-14-70</i>	<i>Billie</i>			
<b>FINAL</b>	<i>8/5/70</i>	<i>J. Barbato</i>			

*Exc*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-2-69	OK slab - Rado
3-11-70	Roof nail - Barbato
7-2-70	The Wall Mail <span style="float: right;">B. White</span>
	<div style="display: flex; justify-content: space-between;"> <span>COMPLETE AND OK</span> <span>INSPECTOR</span> </div>

*R 267 F1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*R 370 F 361-507 file*

**BLDG. #11**

<b>PERMIT NO.</b> <b>G-4447</b>	<b>LOCATION</b> <b>6001 - Riverside Blvd. A-3 (40)</b>
<b>DATE</b> <b>Aug-20-69</b>	<b>PURPOSE</b> <b>Const. 4-unit apartment in apt. complex</b>
<b>ZONE</b> <b>R-3</b>	<b>OWNER</b> <b>ARCH'T</b> <b>(See master card for additional info.)</b> <b>CONTR</b>

<b>VAL.</b>	<b>STORIES</b> <b>2</b>	<b>ROOMS</b>	<b>APTS.</b> <b>4</b>	<b>2,334 2nd flr.</b> <b>1,522 sq. ft.</b>
-------------	----------------------------	--------------	--------------------------	---

<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b> <b>V No Hr.</b> <b>V 1 Hr.</b>	<b>OCCUPANCY GROUP</b> <b>H-1</b>	<b>PHONE (O) (C)</b> <b>487-2570</b>
--------------	-------------	---	-----------------------------------	---

<b>FORM</b>	<i>10-13-69</i>	<i>Field</i>
-------------	-----------------	--------------

<b>JOIST</b>		
--------------	--	--

<b>FRAME</b>	<i>4-16-70</i>	<i>Barbato</i>
--------------	----------------	----------------

<b>SHEET ROCK</b>	<i>4-21-70</i>	<i>Barbato</i>
-------------------	----------------	----------------

<b>FINAL</b>	<i>8/21/70</i>	<i>Barbato</i>	<i>Em</i>
--------------	----------------	----------------	-----------

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
11-3-69	OK slab <span style="float: right;">Sails</span>
12-5-69	OK slab <span style="float: right;">Sails</span>
3-6-70	OK roof rail <span style="float: right;">Basement</span>
	<div style="display: flex; justify-content: space-between;"> <span>COMPLETE AND OK</span> <span>INSPECTOR</span> </div>



R 2127 F1-59

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS *R 290 F 301-304 Fld*  
BLDG. #12

PERMIT NO. <b>G-4447</b>	LOCATION <b>6001 - Riverside Blvd. A-3 (40)</b>
DATE <b>Aug-20-69</b>	PURPOSE <b>Const. 4-unit apartment in apt. complex</b>
ZONE <b>R-3</b>	OWNER
	ARCH'T <b>(See master card for additional info.)</b>
	CONTR

VAL.	STORIES <b>2</b>	ROOMS	APTS. <b>4</b>	<b>1,500 2nd flr.</b>
				<b>1,500 sq. ft.</b>

INSP.	DATE	BLDG. V No Hr. TYPE V 1 Hr.	OCCUPANCY GROUP <b>H-1</b>	PHONE (O) (C) <b>487-2570</b>
-------	------	--------------------------------	-------------------------------	----------------------------------

FORM	<i>10-13-69</i>	<i>Biddle</i>
JOIST		
FRAME	<i>1-6-70</i>	<i>Biddle</i>
SHEET ROCK	<i>4-9-70</i>	<i>Burlotto</i>
FINAL	<i>8/31/70</i>	<i>J. Burlotto</i>

DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
11-21-69	Pk slab	Rills
3-5-70	Pk roof rail	Bustuta
4-13-70	Pk wall rail	Bustuta
	COMPLETE AND OK	INSPECTOR

R267 F1-59

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

R290 F261-341 file

BLDG. #13

PERMIT NO. G-4447	LOCATION 600 <sup>1</sup> / <sub>2</sub> - Riverside Blvd. A-3 (40)
DATE -20-69	PURPOSE Const. 4-unit Apt. in Apartment complex
ZONE R-3	OWNER ARCH'T (See master card for additional info.) CONT'R

VAL. \$	STORIES 2	ROOMS	APTS. 4	2,334 2nd flr. 1,522 sq. ft.
INSP.	DATE	BLDG. TYPE V No Hr. V 1 Hr.	OCCUPANCY GROUP H-1	PHONE (O) (C) 487-2570
FORM	10-13-69 <i>Belle</i>			
JOIST				
FRAME	4-14-70 <i>Belle</i>			
SHEET ROCK	4-20-70 <i>Belle</i>			
FINAL	8/5/70 <i>Belle</i>			

*Ent*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-2-69	OK slab - Peds
3-9-70	OK roof panel      Bultato
4-2-70	OK roof wall panel      Bultato
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>

*R-290 F-1-59*  
**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

*R-290 F-361-364 file*  
**TYPE BUILDINGS**

**BLDG. #14**

<b>PERMIT NO.</b> G-4447	<b>LOCATION</b> 6001 - Riverside Blvd. A-3 (40)				
<b>DATE</b> Aug-20-69	<b>PURPOSE</b> Const. 8-unit apartment in apt. complex				
<b>ZONE</b> R-3	<b>OWNER</b>				
	<b>ARCH'T</b> (See master card for additional info.)				
	<b>CONT'R</b>				
<b>VAL.</b>	<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b> 8	4,192 2nd flr. 4,192 sq. ft.	
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b> V No Hr. V 1 Hr.	<b>OCCUPANCY GROUP</b> H-1	<b>PHONE (OL) (C)</b> 487-2570	
<b>FORM</b>	<i>10-10-69 file</i>				
<b>JOIST</b>					
<b>FRAME SHEET ROCK</b>	<i>4-70 Barbato</i>				
<b>FINAL</b>	<i>4-9-70 Barbato</i>				
	<i>8/31/70 J Barbato</i>				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-2-69	OK slab - Rolo
3-5-70	OK roof nail <span style="float: right;">Dobson</span>
4-2-70	OK 1/2 roof & wall <span style="float: right;">Dobson</span>
COMPLETE AND OK	INSPECTOR

*R-267 F1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*R-240 F-201 304 JCL*

**BLDG. #15**

<b>PERMIT NO.</b> G-4447		<b>LOCATION</b> 600E - Riverside Blvd. A-3 (40)			
<b>DATE</b> Aug-20-69		<b>PURPOSE</b> Const. 8-unit apartment in apt. complex			
<b>ZONE</b> R-3		<b>OWNER</b>			
		<b>ARCH'T</b> (See master card for additional info.)			
		<b>CONT'R</b>			
<b>VAL.</b>		<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b> 8	3,596 2nd flrs. 3,596 sq. ft.
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>V No Hr.</b> V 1 Hr.	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b> H-1 487-2570
<b>FORM</b>	<i>10-13-69 file</i>				
<b>JOIST</b>					
<b>FRAME</b>	<i>4/1-70 J Barbato</i>				
<b>SHEET ROCK</b>	<i>4-7-70 file</i>				
<b>FINAL</b>	<i>8/21/70 J Barbato</i>				

*Enc*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
12-5-69	G. slab	Kills
3-6-70	pk. long nail	Burlington
3-23-70	Roof & wall joint	Burlington
	COMPLETE AND OK	INSPECTOR



*K267 F1-59*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

*R290 F261-364 file*

**BLDG. #16**

<b>PERMIT NO.</b> G-4447	<b>LOCATION</b> 6001 - Riverside Blvd. A-3 (40)
<b>DATE</b> Aug-20-69	<b>PURPOSE</b> Const. 2-unit apartment in apt. complex
<b>ZONE</b> R-3	<b>OWNER</b>
	<b>ARCH'T</b> (See master card for additional info.)
	<b>CONT'R</b>

<b>VAL.</b>	<b>STORIES</b> 2	<b>ROOMS</b>	<b>APTS.</b> 2	<b>1,167 2nd flr.</b> <b>761 sq. ft.</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b> V 1 Hr.	<b>OCCUPANCY GROUP</b> H-1	<b>PHONE (O) (C)</b> 487-2570
<b>FORM</b>	<i>3-9-70</i>	<i>Burbato</i>		
<b>JOIST</b>				
<b>FRAME SHEET ROCK</b>	<i>4-7-70</i>	<i>Pullin</i>		
	<i>4-16-70</i>	<i>Burbato</i>		
<b>FINAL</b>	<i>8/31/70</i>	<i>J. Burbato</i>		

*Enc*

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
12-5-09	Pl. Shat
5-9-70	ok sup nail
	COMPLETE AND OK

*Rick  
Bullock*

INSPECTOR