



RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
6321 - Driftwood Street		6660 - Haven side Drive		3	
LEGAL DESCRIPTION					
Lot 71 Land Park Rivera #2					
TITLE AND NAME		ADDRESS		ZIP	
Lee Basford		6660 - Haven side Drive		CITY LIC. NO.	
GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.	
MECH. CONTR.		ARCH. ENGR.		OWNER	
Mr Sam Parker		5224 - Virginia Way		CONST. LOAN LENDER	
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT	
NO. OF STORIES		ROOF CONSTR.		AREA 1st FLOOR	
TOTAL AREA		C.S.D.		C.I. CASE	
ISSUED BY		DATE		CERTIFICATE OF OCCUPANCY	
1862 Sq. Ft.		1862 Sq. Ft.		1862 Sq. Ft.	
EXISTING BLDG'S SAME LOT		TREES RMVD.		HOW USED	
579 - gar.		579 - gar.		579 - gar.	

NATURE OF WORK:-		Const. dwlg. & att. gar. & cov. patio	
PERMIT NO. S.P. -		R-2759	
ISSUED BY		MICROFILM RECORD	
ISSUANCE DATE		1-11-66	
VALUATION		\$ 18,400.00	
R.O.F. FEE		\$	
JOB FILE		REEL NO. 184	
PLANS AND APPLICATION		FRAME NO. 478	
INSPECTION RECORD		REEL NO. TO	
FRAME NO. TO		483	
S.M.I. FEE		\$	
PLAN CK. FEE		\$	
SEWER INCL. FEE		\$	
PERMIT FEE		\$ 64.00	
TOTAL FEES		\$	
Dwelling		REMARKS AND/OR VARIANCES	
		R4967123 - final	