

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
3700 Belden St.		6			
LEGAL DESCRIPTION					
Del Paso Hghts. Lot 12					
TITLE AND NAME		ADDRESS			
1/c		ZIP			
GEN. CONTR.		CITY LIC. NO.			
Owner		TEL. NO.			
ELEC. CONTR.		ELECTRICAL BY			
		DATE			
PLBG. CONTR.		PLUMBING BY			
		DATE			
MECH. CONTR.		MECHANICAL BY			
		DATE			
ARCH. ENGR.		CERTIFICATE OF OCCUPANCY			
OWNER		ISSUED BY			
Sissler Const.		DATE			
2223 Dale Ave.		CONST. LOAN LENDER			
BLDG. WIDTH		TOTAL HEIGHT		NO. OF STORIES	
BLDG. LENGTH		ROOF CONSTR.		AREA 1st FLOOR	
REAR YARDS		TOTAL AREA		C.S.D.	
SIDE YARDS		1,423		C.I. CASE	
SET BACK REQ.		CENSUS TRCT. NO.		EXISTING BLDG'S SAME LOT	
USE ZONE		1		HOW USED	
PARK'G REQ.		SPACES		TREES RMVD.	
NO. OF STORIES		TOTAL AREA		EXISTING BLDG'S SAME LOT	

NATURE OF WORK:- Const. dwelling & att. garage

PERMIT NO. S.P. - H-4157		ISSUED BY	
ISSUANCE DATE 11-4-71		PLANS AND APPLICATION	
VALUATION \$21,100.00		REEL NO. 501 TO 507	
R.U.F. FEE \$		FRAME NO. 025- (Dmg) TO	
S.M.I. FEE \$		REEL NO. 501 TO 507	
PLAN CK. FEE \$		INSPECTION RECORD	
SEWER INCL. FEE \$		JOB FILE	
PERMIT FEE \$84.00		FRAME NO. 025- (Dmg) TO	
TOTAL FEES \$		REEL NO. 501 TO 507	
		MICROFILM RECORD	
REMARKS AND/OR VARIANCES		Dwelling	