



RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO. \_\_\_\_\_ JOB ADDRESS **8327 Caribbean Way** INSPECTION AREA **A-1**

LEGAL DESCRIPTION **8327 Caribbean Way** OCCUP. GR. \_\_\_\_\_ CONST TYPE \_\_\_\_\_ VAR. NO. \_\_\_\_\_ FIRE ZONE \_\_\_\_\_

TITLE AND NAME **Lot 1117 College Greens #1** ADDRESS \_\_\_\_\_ CITY LIC. NO. \_\_\_\_\_ TEL. NO. \_\_\_\_\_

GEN. CONTR. **Owner** ELEC. CONTR. \_\_\_\_\_ PLBG. CONTR. \_\_\_\_\_ MECH. CONTR. \_\_\_\_\_ ARCH. ENGR. \_\_\_\_\_

OWNER **College Greens** CERTIFICATE OF OCCUPANCY \_\_\_\_\_ ISSUED BY \_\_\_\_\_ DATE \_\_\_\_\_

CONST. LOAN LENDER \_\_\_\_\_

BLDG. WIDTH \_\_\_\_\_ BLDG. LENGTH \_\_\_\_\_ TOTAL HEIGHT \_\_\_\_\_ NO. OF STORIES \_\_\_\_\_ ROOF CONSTR. \_\_\_\_\_ AREA 1st FLOOR \_\_\_\_\_ TOTAL AREA \_\_\_\_\_ C.S.D. \_\_\_\_\_ C.I. CASE \_\_\_\_\_

SIDE YARDS \_\_\_\_\_ REAR YARDS \_\_\_\_\_ SET BACK REQ. \_\_\_\_\_ USE ZONE \_\_\_\_\_ PARK'G REQ. \_\_\_\_\_ SPACES \_\_\_\_\_ TREES RMVD. \_\_\_\_\_ EXISTING BLDG'S SAME LOT \_\_\_\_\_ HOW USED \_\_\_\_\_

NATURE OF WORK: **Const dwelling and garage Plan 406**

PERMIT NO. S.P. **G-741**

ISSUED BY \_\_\_\_\_

ISSUANCE DATE **6-20-68** VALUATION **\$ 15,600**

PLANS AND APPLICATION REEL NO. **241** FRAME NO. **22** TO \_\_\_\_\_

INSPECTION RECORD REEL NO. **241** FRAME NO. **290** TO \_\_\_\_\_

JOB FILE REEL NO. **234** FRAME NO. **156** TO **113**

PLAN CK. FEE \$ \_\_\_\_\_ SEWER INCL. FEE \$ \_\_\_\_\_ PERMIT FEE \$ **55.00**

TOTAL FEES \$ \_\_\_\_\_

REMARKS AND/OR VARIANCES **8925249 - final**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_