



RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
8620 - Glenroy Way		1		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
Lot 846 Glenbrook #8					
TITLE AND NAME		ADDRESS		CITY LIC. NO.	
Besco		Same		383-9315	
GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.	
MECH. CONTR.		ARCH. ENGR.		OWNER	
Valbrook, Inc.		2777 - Alvarado St.		CONST. LOAN LENDER	
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT	
1		5		Rooms	
NO. OF STORIES		AREA 1st FLOOR		TOTAL AREA	
1		1593 sq. ft.		C.S.D.	
SIDE YARDS		REAR YARDS		SET BACK REQ.	
USE ZONE		PARK'G REQ.		SPACES	
R-1		TREES RMVD.		EXISTING BLDG'S SAME LOT	
HOW USED		475 gar.		C.I. CASE	
NATURE OF WORK:-		Const. dwelling & gar. Plan 604 C			

ISSUED BY		ISSUANCE DATE		VALUATION		R.U.P. FEE		S.M.I. FEE		PLAN CK. FEE		SEWER INCL. FEE		PERMIT FEE		TOTAL FEES			
R-7962		Jul. 18-67		\$ 15,600.00		\$		\$		\$		\$		\$ 55.00		\$			
MICROFILM RECORD		PLANS AND APPLICATION		INSPECTION RECORD		JOB FILE		REEL NO. 221		FRAME NO. 140		REEL NO. 197		FRAME NO. 553		REEL NO. 191		FRAME NO. 271	
REMARKS AND/OR VARIANCES		<p style="text-align: center;"><i>05 08F 424 424</i></p>																	
Dwelling																			