

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,830</i>	LOCATION <i>2815 - Santa Cruz Way</i>
DATE <i>10/26/42</i>	PURPOSE <i>General repairs to ducts.</i>
ZONE <i>-</i>	OWNER <i>J. A. Antonuccio.</i>
	ARCH'T. <i>John Loddick.</i>
	CONT'R. <i>John Loddick.</i>

VAL. <i>190⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K.

INSPECTOR