

NOTE: DO NOT COVER OR CONCEAL ANY BUILDING, ELECTRICAL, PLUMBING OR MECHANICAL WORK WITHOUT INSPECTOR'S SIGNATURE IN PROPER PLACE.

INSPECTOR	DATE
B10	FOUNDATION FORMS
E60/B11	UEFR GROUND
B12	CONCRETE SLAB FORMS
P40	PLUMB UNDERFLOOR/SLAB
M30	MECH/UNDERGROUND/SLAB
E61	ELECT UNDERGROUND
E62	ELECT. CONDUIT-SLAB
B13	DO NOT COVER UNTIL INSTALLATION ABOVE HAS BEEN SIGNED
B13	FLOOR JOISTS OR GIRDERS
B13	DO NOT INSTALL SUB FLOOR UNTIL ABOVE HAS BEEN SIGNED
B14/15	INSULATION/WALL/FLOOR
P41	TOP PLUMBING
M31	TOP MECHANICAL/WALL/CEIL.
E63	ROUGH ELECTRICAL/WALL/CEIL.
B19	FRAME
B17	ROOF PLYWOOD NAIL COMM. & APTS.
B18	EXTERIOR LATH/SIDING
B22	DO NOT COVER UNTIL INSTALLATION ABOVE HAS BEEN SIGNED
B22	INT. LATH OR WALL BD. NAILING
B22	DO NOT TAPE PLASTER OR TOP UNTIL ABOVE HAS BEEN SIGNED
E66	SERVICE UNDERGRD CONDUIT
P43	SEWER SERVICE
P42	WATER SERVICE
P46	SPRINKLER SYSTEM
P46	DO NOT COVER UNTIL INSTALLATION ABOVE HAS BEEN SIGNED
P47/MS	GAS TEST
P48	TEMP GAS ISSUED
E68	POWER POLE
E67	TEMP. POWER #
P47	GAS TEST
P51	PLUMBING PRE-GUNITE
P52	PLUMBING PRE-DECK
E70	ELECTRICAL PRE-GUNITE
E71	ELECTRICAL PRE-DECK
E72	ELECTRICAL UNDERGRD
E72	DO NOT COVER UNTIL INSTALLATION ABOVE HAS BEEN SIGNED
E72	ENFRYRY COMPLIANCE CERTIFICATE TO BE ON FILE PRIOR TO FINAL APPROVAL.

BUILDING SITE ADDRESS
3117 Desiderata

ASSESSOR PARCEL NO. 079-0152-216
NAME OF APPLICANT ABC...
ADDRESS ...
LICENSED CONTRACTOR ...
PROPERTY OWNER ...
ARCH. ENGR ...

NO. OF STORIES ... **NO. OF ROOMS** ... **ROOF COVERING** ... **AREA 1ST FLOOR** ... **TOTAL AREA** ... **GARAGE AREA** ... **PATIO AREA** ... **USE ZONE** ... **STREET WIDTH** ...

THIS PERMIT IS FOR: BUILDING MECHANICAL PLUMBING ELECTRICAL SITE FIRE

NATURE OF WORK IN DETAIL
 Demo only of burned roof structure

FLOOD STATUS ... **SPECIAL CONDITIONS ATTACHMENTS** ...

CITY OF SACRAMENTO BUILDING INSPECTION DIVISION 264-5191

WORKER'S COMPENSATION DECLARATION

I hereby affirm under penalty of perjury one of the following declarations:

I have and will maintain a certificate of consent to self-insure for workers' compensation as provided for by Section 3700 of the Labor Code, for the performance of work for which the permit is issued.

I have and will maintain workers' compensation insurance, as required by Section 3700 of the Labor Code, for the performance of the work for which this permit is issued. My workers' compensation insurance carrier and policy number are:

Carrier: ...
 Policy Number: AWC42025802

(This section need not be completed if the permit is for one hundred dollars (\$100) or less) I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the workers' compensation laws of California and agree that if I should become subject to the workers' compensation provisions of Section 3700 of the Labor Code, I shall forthwith comply with those provisions.

DATE ... **APPLICANT** ... **SIGNATURE** ...

ISSUED BY:	VALUATION	DATE ISSUED	BUILDING PERMIT FEE	PLAN CHECK/PROC FEE	S.M.I. FEE	CONST. EXCISE TAX	CITY BUS LICENSE	TECH. FEE	WATER DEV. FEE	CITY SEWER DEV. FEE	REG. SEWER FEE	RESIDENTIAL CONST. TAX	TOTAL FEES
SLC	\$ 8000	9-17-99	\$	\$	\$	\$	\$	\$	\$	\$	\$	\$	\$

THIS PERMIT SHALL EXPIRE BY LIMITATION IF WORK AUTHORIZED IS NOT COMMENCED WITHIN 180 DAYS

Sacramento Fire Department - Incident Report

Incident No : 990024077 Call# : 99054193 Date: 06/11/99 Time: 15:51
Address : 3117 OCCIDENTAL DR
Type : 11 BUILDING FIRE
Action Taken: 11 RESCUE, VENTILATION, EXTINGUISH, SALVAGE, OH
Property : APARTMENTS: APT:3-6 UNIT
UBC : HOTELS APT HOUSES CONVENTS

Weather : 68 Degrees / Clear
Resources : 1 Engine
 : 2 Other Apparatus

Fire Casualties : None

Fire Damage : Confined to structure of origin
Smoke Damage : Confined to structure of origin
Property Loss : \$100,000 Contents Loss : \$55,000
Property Value : \$250,000 Contents Value: \$115,000
Area of Origin : Insufficient information to classify
Caused by : No equipment involved
Form of Heat : Undetermined
Ignition Factor : Undetermined
Type of Material : Undetermined
Form of Material : Undetermined
Type of Material : Undetermined
Form of Material : Undetermined
Other Factors : Acts or Omissions Insufficient information
Extinguished by : Water from hydrant, draft, standpipe
Structure Type : Building with one specific property use
Structure Status : In use
 : Occupied
Construction Type: Type V - Wood Frame
Roof Type : Wood shake - untreated
Number of Stories: 2

Level: A01

Detector Type : No detector

Extinguishing Sys: No extinguishing system

Report Author : F174