

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 3813 Fig Street				INSPECTION AREA	6
LEGAL DESCRIPTION Lot #18 Blk. 11 East Del Paso Hgts.							
TITLE AND NAME 1/3		ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	
GEN. CONTR. Owner							
ELEC. CONTR.							
PLBG. CONTR.							
MECH. CONTR.							
ARCH. ENGR.							
OWNER Mel Longshore		2890 Del Paso Blvd.					
CONST. LOAN LENDER							
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.
						864	
							CENSUS TRCT. NO.
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT
			R-1				HOW USED

NATURE OF WORK:- Const. Dwlg. & carport

PERMIT NO. S.P. - F-530		MICROFILM RECORD		ISSUED BY	
ISSUANCE DATE	5/12/65	REEL NO. APPLICATION	REEL NO. 168	FRAME NO. 391	TO 394
VALUATION	\$ 7,300	INSPECTION RECORD	REEL NO. 525	FRAME NO. 576	TO 576
R.D.F. FEE	\$	JOB FILE	REEL NO.	FRAME NO.	TO
S.M.I. FEE	\$				
PLAN CK. FEE	\$				
SEWER INCL. FEE	\$				
PERMIT FEE	\$				
TOTAL FEES	\$	REMARKS AND/OR VARIANCES			