

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 20 Birty Ct.					INSPECTION AREA 1	FINAL INSPECTIONS		
LEGAL DESCRIPTION Glenbrook #10 Lot 1069					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY <i>Linsen</i>	DATE 11-13-69
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR. Besco										
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER Valbrook, Inc.			2777 Alvarado St.						CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
			1			1,525				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:- **Const. dwelling and att. garage**

PERMIT NO. S.P. - G-3741	MICROFILM RECORD				
ISSUED BY					
ISSUANCE DATE 6-11-69	PLANS AND APPLICATION	REEL NO. 262	FRAME NO:- 19	TO	
VALUATION \$ 15,100.00	INSPECTION RECORD <i>Condon</i>	REEL NO.	FRAME NO:-	TO	538
R.D.F. FEE \$	JOB FILE	REEL NO. B4168537	FRAME NO:-	TO	538
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$ 55.00	REMARKS AND/OR VARIANCES				
\$	Dwelling				
\$					
TOTAL FEES \$					

