



RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
818 Lisbon Way		5-C		FINAL INSPECTIONS	
LEGAL DESCRIPTION					
Lot 46, Larchmont Valley HI #1					
TITLE AND NAME		ADDRESS		ZIP	
Larchmont Valley HI #2		Sacto Inn Plaza		1087	
GEN. CONTR.		CITY LIC. NO.		TEL. NO.	
Owner					
ELEC. CONTR.		PLUMBING BY		DATE	
		Barbato		1/28/66	
PLBG. CONTR.		MECHANICAL BY		DATE	
		Barbato		1/28/66	
MECH. CONTR.		CERTIFICATE OF OCCUPANCY		CONSTR. LOAN LENDER	
		Larchmont Valley HI #2		Sacto Inn Plaza	
ARCH. ENGR.		BLDG. WIDTH		BLDG. LENGTH	
		gar. 450		TOTAL HEIGHT	
NO. OF STORIES		ROOF CONSTR.		AREA 1st FLOOR	
		TOTAL AREA		C.S.D.	
C.I. CASE		EXISTING BLDG'S SAME LOT		HOW USED	
		1087			
SIDE YARDS		REAR YARDS		SET BACK REQ.	
USE ZONE		PARK'G REQ.		SPACES	
				TRES RMVD.	
NATURE OF WORK:-		Const. dwelling and garage, MP #61			

PERMIT NO. S.P.	F1167	ISSUED BY	MICROFILM RECORD
ISSUANCE DATE	7/19/65	PLANS AND APPLICATION	REEL NO. R169 FRAME NO: F579 TO 587
VALUATION	\$ 11,100.	INSPECTION RECORD	REEL NO. R173 FRAME NO: F358 TO
R.O.F. FEE	\$	JOB FILE	REEL NO. TO
S.M.I. FEE	\$		FRAME NO: (Comb) R536R218
PLAN CK. FEE	\$		
SEWER INCL. FEE	\$		
PERMIT FEE	\$ 43.	REMARKS AND/OR VARIANCES	
TOTAL FEES	\$		