

2180 7 276-287

| | | | | | |
|----------------------|----------|--|-----------------|---------------|---------|
| Lot 358 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$49.00 |
| Glenbrook #4 | | TYPE BUILDINGS R316 R15 | | | |
| PERMIT NO. F-7194 | LOCATION | 2824 - Sarina Court | | A-1 | |
| DATE May 4-67 | PURPOSE | Const. dwlg. & att. gar. Plan 403 A | | | |
| | OWNER | Wilbrook Inc. 2777-Alvarado St., | | | |
| ZONE R-1 | ARCH'T | San Leandro | | | |
| | CONTR | Besco same 363-7315 | | | |
| VAL. \$13,800. | STORIES | ROOMS | APTS. | 500-gar. | SIZE |
| | | | | 1394 sq. ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | 5-9-67 | Court | | | |
| JOIST | 5-30-67 | Court | | | |
| FRAME | 6-3-67 | Garage | | | |
| SHEET ROCK | 6-3-67 | Court | | | |
| FINAL | 8-15-67 | Garage | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 5-16-67 | All slab Crest |
| 9-11-67 | Pl. removed. not ready Bris |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK INSPECTOR |