

Lot 870

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$55.00

Glenbrook #9

TYPE BUILDINGS

R191 F 271-276 plan

R 197 F553 rev.

| | |
|----------------------|--|
| PERMIT NO. F-8784 | LOCATION 89 - Waterglen Circle. A-1 |
| DATE 10-17-67 | PURPOSE Const. dwlg. & att. gar. Plan 604 |
| ZONE R-1 | OWNER Wilbrook, Inc. 2777-Alvarado St. |
| | ARCH'T San Leandro, Calif. |
| | CONT'R Besco Same 383-9315 |

| | | | | |
|---------------|--------------|---------------|------------------------------------|---------------|
| VAL. #15,600. | STORIES 1 | ROOMS 5 | APTS. 475 gar. 1,593 sq. ft. | SIZE |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | 10-27-67 | Calloway | | |
| JOIST | 11-9-67 | Calloway | | |
| FRAME | 1-3-68 | Gold | | |
| SHEET ROCK | 1-9-68 | Rials | | |
| FINAL | 2-3-68 | Rials | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 11.6.67 | R/C main beam Berleuts |
| 11.8.67 | P/Guest - roadway Berleuts |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK INSPECTOR |