

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-444</i>	LOCATION <i>1058 - Perkins Way</i>			
DATE <i>12/12/39</i>	PURPOSE <i>Erect new dwg for</i>			
ZONE <i>2</i>	OWNER <i>John Fernandez</i>			
ARCH'T.	CONTR. <i>Owner</i>			
VAL. <i>4000</i>	STORIES	ROOMS <i>5</i>	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS	BOILER ROOMS	<i>1140'</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>0.350</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
12/15/39	1 ST N.S.P. Frame in place ^{OK} R.W. Campbell
1/22/40	2 ND N.S.P. Frame ^{OK} R.W. Campbell
	<p data-bbox="322 911 470 955">COMPLETE AND O. K.</p> <p data-bbox="1263 928 1420 955">INSPECTOR</p>