

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-23289</i>	LOCATION <i>1419. Tenight Way</i>			
DATE <i>9-21-48</i>	PURPOSE <i>Repair fire damage</i>			
ZONE	OWNER <i>Dr. D. Jones</i>			
	ARCH'T.			
	CONTR. <i>C. R. Morris</i>			
VAL. <i>\$2000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK--REMARKS
	<p data-bbox="308 843 431 881">COMPLETE AND O. K.</p> <p data-bbox="1124 857 1252 881">INSPECTOR</p>

