


BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. 6833	LOCATION N East Du Serrail 1111 Robertson Way		
DATE 9/4/30	PURPOSE Fr St Res garage	ROOMS 5	APTS. 1
ZONE 2A	OWNER Land Du Serrail	PHONE	
	ARCH'T Joseph J P Williams		
	CONTR Over		
	VAL. 4750	STORIES 1	SIZE 34' x 40' 2"

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Jolsts						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK-REMARKS
9/5-30	1 st Jump Forms in place OK P.H. Reuter
7/25-30	2 " Frame & " " " P.H. Reuter
7/31-30	3 " Int & Ext Lath OK P.H. Reuter
11/18-30	4 " Finished OK
	Certificate of occupancy issued
COMPLETED AND O.K.	 INSPECTOR