

9131 2504-514

Lt. 16

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$49.00

Greenhaven 70 #1 TYPE BUILDINGS

| | | | | |
|----------------------|---|-------------------|-------------------|----------------------|
| PERMIT NO. E-5475 | LOCATION 866 - Parklin Avenue | | A-3 | |
| DATE Oct. 28-63 | PURPOSE Const. dwelling & attached garage | | | |
| ZONE R-1 | OWNER John K. Harris | | 1140 - Fay Circle | |
| | ARCH'T | | | |
| | CONTR Owner | | Same GA 8-2485 | |
| VAL. \$13,600. | STORIES 1 | ROOMS 6 | APTS. 437-gar. | SIZE 1,409 sq.ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | <i>10-30-63</i> | <i>Fully</i> | | |
| JOIST | <i>11-8-63</i> | <i>Barbato</i> | | |
| FRAME | <i>12-9-63</i> | <i>Barbato</i> | | |
| SHEET ROCK | <i>12-16-63</i> | <i>Barbato</i> | | |
| FINAL | <i>2-11-64</i> | <i>C. Hammond</i> | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------------------|--------------------------------------|
| 3-5-64 | PT Exhaust duct must be 1" |
| | from wood. Rinix Chest Gas Cook |
| | above chest A unumers |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |