

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-9289</i>	LOCATION <i>609 Swanton St.</i>			
DATE <i>10/8/41</i>	PURPOSE <i>Erect new dwlg. & gas</i>			
ZONE	OWNER <i>Mary. Dunning</i>			
	ARCH'T. <i>Harold Dunning</i>			
	CONTR. <i>Harold Dunning</i>			
VAL. <i>4200.00</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>12'0" x 1'</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 30'</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
10/8/41	1 ST INSP. Forms in place ^{OK} A.W. Campbell
10/20/41	2 ND INSP. Frame ^{OK} A.W. Campbell
11/3/41	3 RD INSP. INT & EXT LATH ^{OK} A.W. Campbell
12/24/41	4 TH INSP. Dwg & Garage Completed ^{OK}
12/24/41	<p>COMPLETE AND O. K. <i>Alfred W. Campbell</i> INSPECTOR</p>