

355 - Paimense Way

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4461</i>	LOCATION <i>355 - 37th Street</i>			
DATE <i>6/19/36</i>	PURPOSE <i>Erect new res. & garage</i>			
ZONE <i>2 - Fam -</i>	OWNER <i>Harold Leak.</i>			
ARCH'T.	CONTR. <i>J. E. Edenhofer 3030-17th St.</i>			
VAL. <i>6000⁰⁰</i>	STORIES <i>1 1/2</i>	ROOMS <i>7</i>	APTS.	SIZE <i>Duplex</i>
LIGHT SHAFTS	ELEVATOR SHAFTS	VENT SHAFTS	BOILER ROOMS	<i>Area 1819⁰¹ @ 3.50</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
6/24	1 st Floor Formwork OK Painter
8/29-	2 " Frame " Painter
9-11-	3 " Lath " Painter
12/2	4 " Finished & OK
	Certificate of Occupancy
	signed
	Painter
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>