

R232FR43

Lot 928		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$49.00
Glenbrook Unit #9		TYPE BUILDINGS			R229F60-70
PERMIT NO. F-9447	LOCATION 56 - Waterglen Circle A-1 (52)				
DATE 1-31-68	PURPOSE	Const. dwlg. & att. gar. #100			
ZONE R-1	OWNER	Edificios, Inc. 2777 Alvarado St. San Leandro, CA.			
	ARCH'T				
	CONT'R	Besco same 383-9315			
VAL. \$13,900.	STORIES	ROOMS	APTS.	456 sq.ft. SIZE 1383 sq.ft.	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	2-29-68	Dist			
JOIST	3-18-68	Dist			
FRAME	4-16-68	Dist			
SHEET ROCK	4-19-68	Dist			
FINAL	1-25-68	Dist			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3-6-68	Plc slab Rivets
3-13-68	Plc Rivet - Termites in concrete inspect concrete screw rivets
3-14-68	Plc Rivet - Termites in concrete inspect
4-15-68	Plc Rivet - Termites in concrete not ready Rivets
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>