

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5827</i>	LOCATION <i>1074 - Perkins Way</i>
DATE <i>6/20/40</i>	PURPOSE <i>Erect new dwg. &amp; gar.</i>
ZONE	OWNER <i>Fred J. Chapin</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>3000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>1200<sup>00</sup></i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>03<sup>00</sup></i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
6/22/40	1 <sup>ST</sup> /NSP. Form replaced <sup>OK</sup> A.W. Campbell
7/29/40	2 <sup>ND</sup> /NSP. Frames . . . . . <sup>OK</sup> A.W. Campbell
7/31/40	3 <sup>RD</sup> /NSP. Int & Ext Latex <sup>OK</sup> A.W. Campbell
9/30/40	4 <sup>TH</sup> /NSP. Dwg & Garage Completed <sup>OK</sup> A.W. Campbell
9/20/40	COMPLETE AND O. K. <i>Allen A. Campbell</i> INSPECTOR