

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5827</i>	LOCATION <i>1074 - Perkins Way</i>
DATE <i>6/20/40</i>	PURPOSE <i>Erect new dwg. & gar.</i>
ZONE	OWNER <i>Fred J. Chapin</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>3000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>1200⁰⁰</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>03⁰⁰</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
6/22/40	1 ST /NSP. Form replaced ^{OK} A.W. Campbell
7/29/40	2 ND /NSP. Frames ^{OK} A.W. Campbell
7/31/40	3 RD /NSP. Int & Ext Latex ^{OK} A.W. Campbell
9/30/40	4 TH /NSP. Dwg & Garage Completed ^{OK} A.W. Campbell
9/20/40	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR