

R232 F242

Lot 923		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$49.00
Glenbrook Unit #9		TYPE BUILDINGS			R180 F491-501 R197 F553 REV R195 F314-318 REV
PERMIT NO. F-9442	LOCATION 36 - Waterglen Circle A-1 (52)				
DATE 1-31-68	PURPOSE Const. dwlg. & att. gar. #402				
ZONE R-1	OWNER Barbrook, Inc. 2777 Alvarado St. San Leandro				
	ARCH'T CONTR Besco same 383-9315				
VAL. \$13,100.	STORIES	ROOMS	APTS.	447 gar. size 1327 sq.ft.	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	2-28-68	Reed			
JOIST	3-13-68	Reed			
FRAME	4-10-68	Reed			
SHEET ROCK	4-15-68	Reed			
FINAL	5-29-68	Reed			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3-4-68	ok slab <i>Boiler</i>
4-9-68	OK frame - satisfactory <i>Boiler</i>
	COMPLETE AND OK <span style="float: right;">INSPECTOR</span>