

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-13427</i>	LOCATION <i>9073 - Dwanston Dr.</i>
DATE <i>6/2/45</i>	PURPOSE <i>Remodel attic.</i>
ZONE	OWNER <i>E. E. Arnold</i>
	ARCH'T.
	CON'T'R. <i>M. Wetmore</i>

VAL. <i>875⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE.	CONDITION OF WORK-REMARKS
6/26/45	2 ND LNSP. Frame for Finishing Rd.
	After for Bed Base - Has 8/2 Center Head
	Stairway to same O.K. - Mr Campbell
	3 RD LNSP. Sheet Rock Walls & Ceiling. O.K.
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>