

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 2924 Belmar St.				INSPECTION AREA 1	FINAL INSPECTIONS				
LEGAL DESCRIPTION Glenbrook #2 Lot 180		OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY <i>Hammers</i>	DATE <i>2/18/66</i>				
TITLE AND NAME Besco		ADDRESS 2777 Alvarado St.	ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE				
GEN. CONTR.							PLUMBING BY	DATE			
ELEC. CONTR.							MECHANICAL BY	DATE			
PLBG. CONTR.							CERTIFICATE OF OCCUPANCY				
MECH. CONTR.							ISSUED BY	DATE			
ARCH. ENGR.											
OWNER Barbrook, Inc.	2777 Alvarado St.										
CONST. LOAN LENDER		BLDG. WIDTH		BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES 1	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA 1,232	C.S.D.	C.I. CASE
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED		

NATURE OF WORK:- **Const. dwelling and attached garage Plan 401**

PERMIT NO. S.P. - F-2241	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 180	FRAME NO. 480	TO 489
ISSUANCE DATE 11-8-65	INSPECTION RECORD	REEL NO. 188	FRAME NO. 490	TO
VALUATION \$ 12,400.00	JOB FILE	REEL NO.	FRAME NO.	TO
R.D.F. FEE \$	<i>Combined 84268288 - 289</i>			
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$ 46.00	REMARKS AND/OR VARIANCES			
\$	Dwelling			
\$				
TOTAL FEES \$				

