

1329 Lynette Way

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA 5	FINAL INSPECTIONS		
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
Lot 76 Rio Park									Fuller	11/29/60
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR. Owner										
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER Harold Redgate			5604 Harold						CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
						870 Sq.Ft. (530 gar)				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

NATURE OF WORK:- Const. dwlg & att. garage

PERMIT NO. S.P. - D-4842	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 67	FRAME NO:- 219	TO 224
ISSUANCE DATE 3/4/60	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
VALUATION \$ 8,600.	JOB FILE	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$	R 538 F007 (comb)			
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$ 26.	REMARKS AND/OR VARIANCES			
\$				
\$				
TOTAL FEES \$				

Dwlg.

