

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

|                       |  |  |       |                  |      |
|-----------------------|--|--|-------|------------------|------|
| PERMIT NO.<br>B-38014 |  | LOCATION 51 Taylor Way                     |       |                  |      |
| DATE<br>5-12-53       |  | PURPOSE Erect patio onto rear of dwelling. |       |                  |      |
| ZONE                  |  | OWNER W. D. Reber                          |       |                  |      |
|                       |  | ARCH'T.                                    |       |                  |      |
|                       |  | CONTR. Owner                               |       |                  |      |
| VAL. \$705.00         |  | STORIES                                    | ROOMS | APTS.            | SIZE |
| LIGHT SHAFTS          |  |  |       | ELEVATOR SHAFTS  |      |
| VENT SHAFTS           |  |  |       | BOILER ROOMS     |      |
| OWNER'S INSPECTOR     |  |  |       | SPRINKLER SYSTEM |      |
| LATH                  |  |  |       | GAS VENTS        |      |
| FIRE ESCAPES          |  |  |       | CHIMNEYS         |      |
| STAND PIPES           |  |  |       | SKYLIGHTS        |      |

| DATE | CONDITION OF WORK—REMARKS  |
|------|--|
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      |  |
|      | <p data-bbox="284 866 414 905">COMPLETE<br/>AND O. K.</p> <p data-bbox="1120 878 1251 902">INSPECTOR</p> |