

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 4229 Austin Street		INSPECTION AREA 6	
LEGAL DESCRIPTION Lot 88 Glenwood Park #1					
ADDRESS 4229 Austin Street					
CITY LIC. NO.					
ZIP					
TEL. NO.					
GEN. CONTR. Owner					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER Jere Strizek					
CONST. LOAN LENDER					
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT	
NO. OF STORIES		ROOF CONSTR.		AREA 1st FLOOR	
TOTAL AREA		C.S.D.		C.I. CASE	
SIDE YARDS		REAR YARDS		SET BACK REQ.	
USE ZONE		PARK'G REQ.		SPACES	
TREES RMWD.		EXISTING BLDG'S SAME LOT		HOW USED	
NATURE OF WORK:- Const Dwelling & att carport					

PERMIT NO. S.P. - E-9511	ISSUED BY		MICROFILM RECORD	
ISSUANCE DATE 2-5-65	PLANS AND APPLICATION	REEL NO. 160	FRAME NO. 562	TO
VALUATION \$12,000.00	INSPECTION RECORD	REEL NO. 160	FRAME NO. 553	TO
R.D.F. FEE \$	JOB FILE COMBINE	REEL NO. 160	FRAME NO. 553	TO
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$43.00	REMARKS AND/OR VARIANCES			
TOTAL FEES \$	FORM 2-18-65	Chapin		
	FRAME 3-22-65	Chapin		
	S/R 3-30-65	Chapin		