

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>5307</i>	LOCATION <i>3408 St.</i>		
DATE <i>10/14/29</i>	PURPOSE <i>add 1st fl. to building - enlarge porch garage</i>	ROOMS	APTS.
ZONE	OWNER <i>Mrs. R. D. Driskley</i>	PHONE	
	ARCH'T		
	CONT'R <i>[Signature]</i>		
	VAL. <i>157-</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF	Chimneys	Cement Tests
EX WALL	Joints							
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE

CONDITION OF WORK—REMARKS

2/18/79

1st Use Cement for Additional Stall for Parrots
Garage in place OK

A W Campbell

2/30/79

Completed & OK R H Rector

COMPLETED
AND O.K.

INSPECTOR