

R222 F239

Lot 922		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$55.00
Glenbrook Unit #9		TYPE BUILDINGS		R229 F71-80	
PERMIT NO. F-9440	LOCATION		32 - Waterglen Circle		A-1 (52)
DATE 1-31-68	PURPOSE	Const. dwlg. & att. gar.		#101	
ZONE R-1	OWNER	Brookvale, Inc.		277 Alvarado St. San Leandro, CA.	
	ARCH'T				
	CONTR	Besco	same	383-9315	
VAL. \$15,100.	STORIES	ROOMS	APTS.	462 gar. SIZE 1525 sq.ft.	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	2-14-68	Reps			
JOIST	3-13-68	Reps			
FRAME	4-9-68	Reps			
SHEET ROCK	4-15-68	Reps			
FINAL	5-28-68	Reps			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3. 20.68	ok slab Risks
3.5.68	Hydrant - not ready Risks
	<p>COMPLETE AND OK INSPECTOR</p>