

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-27654</i>	LOCATION <i>1718 - Tenwick Way</i>
DATE <i>3/16/59</i>	PURPOSE <i>Erect new dwelling - 2 gar</i>
ZONE <i>2 - 7 am</i>	OWNER <i>J. E. Roland</i>
	ARCH'T. <i>Owner</i>
	CONTR. <i>Owner</i>

VAL. <i>7800</i>	STORIES <i>1</i>	ROOMS <i>8</i>	APTS.	SIZE
------------------	------------------	----------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS	BOILER ROOMS	<i>2440'</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 350</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
	1 ST Insp. Frame in place <i>PH Renter</i>
5/19/39	2 ND Insp. Frame in place <i>OK M Campbell</i>
5/27/39	3 RD Insp. INT & EXT LATH <i>OK M Campbell</i>
10/2/39	4 TH Insp. Dry & Garage Completed <i>OK</i>
	Issued Final Insp & Cert. of Occup.
	Street Cleaned up <i>OK</i>
10/2/39	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. <i>W. Campbell</i> INSPECTOR </div>